

Field Inspection Photos
2/23/16
Prowers Gas Gathering
Facility 444661



Figure 1 – Ownership and contact information has been posted.



Figure 2 – Looking northeast. Barrels of motor oil have been removed and stained soil excavated.



Figure 3 – West side of facility.



Figure 4 – East side of facility.



Figure 5 – Looking southwest.