

Interim Reclamation Inspection



Photo 1. Photo of well sign.

Interim Reclamation Inspection



Photo 2. Photo taken from east location, facing West. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 3. Photo taken from west location, facing East. Need to remove weeds around all operating oil and gas equipment on location.