

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. Access road traveling through location. Uncertain what this access road is being used for.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. Appears to have perennial growth in some areas of the location.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. Appears to have perennial growth in some areas of the location.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. Access road traveling through location. Uncertain what this access road is being used for.

Final Reclamation Inspection



Photo 5. Photo taken from west location, facing East. Appears to lack vegetative growth in some areas of the location.

Final Reclamation Inspection



Photo 6. Photo taken from center of location. Waste material left behind.