

Construction Inspection



Photo 1. Photo taken from southwest location, facing North. Stormwater and sediment control BMPs installed in center of photo.

Construction Inspection



Photo 2. Photo taken from northwest location, facing East. Stormwater and sediment control BMPs installed in center of photo.

Construction Inspection



Photo 3. Photo taken from north-central location, facing South. Stormwater and sediment control BMPs installed in center of photo.

Construction Inspection



Photo 4. Photo taken from north-central location, facing East. Stormwater and sediment control BMPs installed in center of photo.

Construction Inspection



Photo 5. Photo taken from northeast location, facing South. Stormwater and sediment control BMPs installed in center of photo.

Construction Inspection



Photo 6. Photo taken from southeast location, facing West. Stormwater and sediment control BMPs installed in center of photo.

Construction Inspection



Photo 7. Photo taken from south of well location, facing East. Topsoil stockpile moved south of well location about 30 meters. Sediment control BMPs installed around topsoil stockpile.

Construction Inspection



Photo 8. Photo taken from south of well location, facing North. Topsoil stockpile moved south of well location about 30 meters. Sediment control BMPs installed around topsoil stockpile.