


Photo#1:

View West over Location



Photo#2:

View Down slope over sediment trap, South to base of Fill Slope



February 25, 2016

Inspection Photos WPX Loc# 335070

Photo#3:
Sediment Trap, water cutting under Rock



Photo#4:
Channel forming from water exiting Sed Trap



Photo#5:

View of BMPs at base of Fill Slope at South edge of Location



Photo#6:

View of BMPs at base of Fill Slope at South edge of Location



Photo#7:

Rill erosion commencing on Fill Slope.



Photo#8:

Fill Slope well stabilized, NE side of Location

