



Photo 1. View of the access road facing southward. Roadsides are weedy and musk thistle (*Carduus nutans*) is present and needs control.



Photo 2. View of fencing debris in the northeastern portion of the project area.



Photo 3. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is comprised of re-seed and weedy species such as intermediate wheatgrass (*Thinopyron intermedium*) and Russian thistle (*Salsola tragus*).



Photo 4. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 5. View of the western portion of the project area from the southwestern corner facing northward.



Photo 6. View of fresh disturbance in the southern portion of the project area. This area needs monitoring may need revegetation in fall 2016 if it doesn't revegetate during the 2016 growing season.



Photo 7. View of stormwater erosion that is occurring in the southern portion of the project area. Wattles need to be repaired and new BMPs may need to be installed.