



Photo 1. View of stormwater erosion occurring at the well pad entrance, south of the access road. It is unclear if cobble lined channel was recently stabilized or if it needs additional stabilization. The channel on the right does not appear stabilized and needs BMPs.





Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward.





Photo 3. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing here with intermediate wheatgrass (*Thinopyron intermedium*) and dropseed (*Sporobolus* sp.) as well as weeds such as chicory (*Cichorium intybus*) and kochia (*Kochia scoparia*).





Photo 4. View of the project area from the southwestern corner facing center.





Photo 5. View of the southern portion of the project area from the southwestern corner facing eastward. Salt licks and cattle feeding trough are present.





Photo 6. View of the eastern portion of the project area from the southeastern corner facing northward.