



Photo 1. View of the northern portion of the project area from the northeastern corner facing westward. Poor revegetation along slopes needs to be monitored and re-seeded in fall 2016 if it is not progressing during the 2016 growing season.



Photo 2. View of the project area from the northeastern corner facing center. Sand dropseed (*Sporobolus* sp.) is growing at the bottom of the cut slope.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Poor revegetation here, may need re-seeding in fall 2016 if it is not progressing.



Photo 4. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing here with intermediate wheatgrass (*Thinopyron intermedium*), soft brome (*Bromus inermis*), and crested wheatgrass (*Agropyron cristatum*).



Photo 5. View of kochia (*Kochia scoparia*) debris in the western portion of the project area that needs to be removed.