

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
03/01/2016  
Document Number:  
671106506  
Overall Inspection:  
**ACTION REQUIRED**

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>202912</u>	<u>320177</u>	<u>MONTOYA, JOHN</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #210  
City: AURORA State: CO Zip: 80016

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections
Condill, J.B.		jbcrog@aol.com	
Espinosa, Bill		billespionsa30@yahoo.com	Inspections

**Compliance Summary:**

QtrQtr: NWSW Sec: 29 Twp: 2S Range: 62W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/07/2007	200128926	PR	PR	<b>ACTION REQUIRED</b>			Yes
11/16/2005	200080554	PR	PR	<b>ACTION REQUIRED</b>		<b>Fail</b>	No
10/14/2004	200061665	PR	PR	SATISFACTORY		Pass	No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
104695	PIT	CL	09/23/1999		-	ANN WALKER 2	CL <input type="checkbox"/>
113207	PIT	CL	09/23/1999		-	AVAILABLE	CL <input type="checkbox"/>
202912	WELL	PR	09/07/1994	OW	001-08317	WALKER ANN 2	PR <input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Lease Road:</b>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TRASH	<b>ACTION REQUIRED</b>	<b>55 GAL DRUM</b>	<b>REMOVE DRUMS</b>	<b>04/05/2016</b>

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
Lube Oil	Pump Jack	<= 1 bbl	<b>SOILED DIRT INSIDE MOTOR MOUNTS AT WELLHEAD, CLEAN UP SOILED DIRT</b>	<b>04/05/2016</b>
Crude Oil	Tank	<= 1 bbl	<b>SOILED DIRT INSIDE BERMS LOOKS LIKE THEY BEEN DRAINING WATER INSIDE BERMS, DIRT NEEDS TO BE SAMPLED</b>	<b>04/05/2016</b>
Crude Oil	Separator	<= 1 bbl	<b>CLEAN UP SOILED DIRT IN SEP HOUSE AND WHERE SCRUBBER HAS BEEN BEIBG DRAINED</b>	<b>04/05/2016</b>

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
SEPARATOR	<b>ACTION REQUIRED</b>	<b>BARBWIRE FENCE DOWN</b>	<b>FIX FENCE AND POST</b>	<b>04/05/2016</b>
WELLHEAD	SATISFACTORY	<b>BARB WIRE FENCE</b>		

<b>Equipment:</b>				
Type: Submersible Pump	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	<b>SE CORNER N39.50980 W-104.21245</b>			
Corrective Action				Date: _____
Type: Bird Protectors	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date: _____
Type: Pump Jack	# 1	Satisfactory/Action Required:	SATISFACTORY	

Comment	SE CORNER N39.50713 W-104.21319		
Corrective Action			Date:
Type: Deadman # & Marked	# 4	Satisfactory/Action Required:	ACTION REQUIRED
Comment	DEADMEN NEED TO BE MARKED OFF WITH POSTS		
Corrective Action	MARK DEADMEN		Date: 4/5/2016
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment	SE CORNER N39.50980 W-104.21245		
Corrective Action			Date:

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	39.507130,-104.213190
S/AR	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_  
 Other (Capacity) \_\_\_\_\_  
 Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Corrective Action	REPAIR BERMS			Corrective Date 04/05/2016
Comment	BERMS NEED TO BE REBUILT			

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	,
S/AR	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_  
 Other (Capacity) \_\_\_\_\_  
 Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Corrective Action	REPAIR BERMS			Corrective Date 04/05/2016
Comment	BERMS IN DIS-REPAIR			

<b>Venting:</b>	
Yes/No	NO
Comment	

<b>Flaring:</b>			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 202912

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 202912 Type: WELL API Number: 001-08317 Status: PR Insp. Status: PR

**Producing Well**

Comment:

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment:   
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_  
Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
Land Use: \_\_\_\_\_  
Comment:   
1003a. Waste and Debris removed? Pass  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? Pass  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? Pass  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? Pass  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass  
1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
	montoyaj	03/01/2016
	montoyaj	03/01/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671106507	BATTERY SIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796491">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796491</a>
671106508	SOILED DIRT LOAD LINE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796492">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796492</a>
671106509	SOILED DIRT BETWEEN TANKS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796493</a>
671106510	SOILED DIRT BEHIND PROD TANK	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796494">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796494</a>
671106511	BREECH IN BERMS LOOKS LIKE BEEN DRAINING WATER	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796495">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796495</a>
671106512	REPAIR BERMS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796496</a>
671106513	TRASH NAND FENCE DOWN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796497">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796497</a>
671106514	SOILED FROM SCUBBER DRAIN LINE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796498</a>
671106515	LEAKING DUMP VALVE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796499</a>
671106516	STUFFING BOX LEAKS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796500</a>
671106517	SOILED DIRT SEP HOUSE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796501</a>
671106518	SOILED DIRT SEP	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796502</a>
671106519	WELL SIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796503">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796503</a>
671106520	SOILED DIRT MOTOR MOUNT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796504">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796504</a>
671106521	SOILED DIRT WELLHEAD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796505</a>
671106522	SOILED DIRT INSIDE PUMP JACK FRAME	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796506">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796506</a>
671106523	2" VALVE LEAKING	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796507">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796507</a>
671106524	2"LEAKING VALVE	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796508</a>
671106525	HOLES IN PROD TANK	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796509</a>