

Final Reclamation Inspection




Photo 1. Photo taken east of location, facing West. Evidence of well pad. Location lacks vegetative growth- not representative of the reference area, gravel not removed, and waste material on location.

Final Reclamation Inspection




Photo 2. Photo taken south of location, facing North. Evidence of well pad. Location lacks vegetative growth- not representative of the reference area, gravel not removed, and waste material on location.

Final Reclamation Inspection



Photo 3. Photo taken west of location, facing East. Evidence of well pad. Location lacks vegetative growth- not representative of the reference area, gravel not removed, and waste material on location.

Final Reclamation Inspection




Photo 4. Photo taken north of location, facing South. Evidence of well pad. Location lacks vegetative growth- not representative of the reference area, gravel not removed, and waste material on location.

Final Reclamation Inspection



Photo 5. Photo taken from central well location illustrating the lack of vegetative growth and gravel not removed.

Final Reclamation Inspection



Photo 6. Photo taken from well location illustrating waste material (rebar) left behind.

Final Reclamation Inspection



Photo 7. Reference photo taken approximately 30 meter northwest of location illustrating vegetative growth.

Final Reclamation Inspection



Photo 8. Close up reference photo taken approximately 30 meter northwest of location.