



Photo 1. View of the eastern portion of the project area from the southeastern corner facing northward. Rig anchor is needs to be marked.



Photo 2. View of the project area from the southeastern corner facing center.





Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.





Photo 4. View of the western portion of the project area from the southwestern corner facing northward. Kochia (*Kochia scoparia*) needs to be monitored and controlled if it is discouraging revegetation or is growing near project facilities.