



Photo 1. View of the southern portion of the project area from the southwestern corner facing eastward. What appear to be landowner junk and debris is piled up here.



Photo 2. View of the project area from the southwestern corner facing center.



Photo 3. View of western portion of the project area from the southwestern corner facing northward. What appears to be several pieces of landowner junk and equipment are stored here.



Photo 4. View of the northern portion of the project area from the northeastern corner facing westward. Cement debris is piled in the foreground.



Photo 5. View of the eastern portion of the project area from the northeastern corner facing southward. What appears to be surface owner equipment and hay storage is occurring here.