



Photo 1. View of the eastern portion of the project area from the southeastern corner facing northward. It appears that stormwater flows exit the southeastern corner and flow southward. This area should be monitored and BMPs applied if needed.



Photo 2. View of ruts in the well pad approximately 20 inches deep. The well pad surface needs better stabilization.



Photo 3. Another view of rutting within the project area. This needs to be stabilized.



Photo 4. View of the southern portion of the project area from the southeastern corner facing westward. Grasses such as Indian ricegrass (*Achnatherum hymenoides*), squirreltail (*Elymus elymoides*), and western wheatgrass (*Pascopyrum smithii*) are established here.



Photo 5. View of the northern portion of the project area from the northwestern corner facing eastward.