

Inspection Photos
3/3/16
Facility #261309
State of Colorado AS 42-36V



Figure 1 – Lease sign.



Figure 2 – Water intake on northwest corner of pit. Liner is torn above water level.



Figure 3 – Torn liner on northeast pit wall.



Figure 4 – Torn liner on northwest pit wall.



Figure 5 – Bubbles in pit liner and vegetation growing in pit.



Figure 6 – Looking northwest.



Figure 7 – Fencing is in disrepair.