

Antelope Farms #1-24 March 1, 2016 Environmental Inspection – S. Arauza



Figure 1 - Tank sign and tank.



Figure 2 – Vegetation growth inside of tank battery berm.



Figure 3 – Stained soil, maintenance issues, and gaps in wildlife protection at skim pit.



Figure 4 - View of produced water pit from northwest corner. Note sagging wildlife protection mesh and tumbleweeds encroaching on pit from the west.



Figure 5 - Oil-stained soil at southeast corner of produced water pit. Note burrows in NE corner of pit.



Figure 6 – Oil-stained soil inside of pit (along south and west walls), vegetation growth and wind-blown weeds accumulating outside of pit along west wall.