

COGCC March 1, 2016 Environmental Inspection of Ann Walker #2 – S. Arauza



Figure 1 - Tank Battery Sign.



Figure 2 - Ann Walker #2 Tank Battery.



Figure 3 – Localized oily waste inside of tank battery berm.



Figure 4 - Oil-stained soil at tank loadout and inside of containment berm, note unused equipment/trash present behind berm.



Figure 5 - Oil stained soil inside of tank battery and gap in berm.



Figure 6 – Absence of vegetation south of tank battery and gap in berm.



Figure 7 - Oil-stained soil, corrosion, and small hole in crude oil AST.



Figure 8 – Berm in need of repair.



Figure 9 - Burrow observed in tank battery berm.



Figure 10 - Oil-stained soil north of production water tank.



Figure 11 - Oil-stained soil beneath leaking valve on crude oil AST.



Figure 12 - Unused equipment/trash at tank battery.



Figure 13 - 55-gallon drum outside of separator shed lacking secondary containment.



Figure 14 - 55-gallon drum outside of separator shed lacking secondary containment.



Figure 15 - Partially-dismantled separator with unused equipment and storage drums lacking secondary containment at separator shed.



Figure 16 - Oil-stained soil at southeast corner of separator shed, note line being used to drain E&P waste from inside of shed.