

Interim Reclamation Inspection

3/3/2016

Operator: Whiting Oil and Gas

Location ID: 433999

Weld County, CO

NESE Section 27 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



03.03.2016 13:33

Figure 1: Photo taken from access road, south of location, facing north. Photo shows location sign.



03.03.2016 14:04

Figure 2: Photo of well #123-37899



Figure 3: Photo of well #123-37956.



Figure 4: Photo of well #123-37898.



Figure 5: Photo of well #123-37953



Figure 6: Photo of well #123-37900



Figure 7: Photo of well #123-37974



Whiting Oil & Gas Corp

Razor 271-3414B

NE, SE, Sec 27, T10N, R58W

Weld County, CO

API# - 0512337901

Emergency # 1-800-723-4608

03.03.2016 14:06

Figure 8: Photo of well #123-37901



Figure 9: Photo of well #123-37949.



Figure 10: Photo taken from the access road at the south end of the location. Photo of culvert and stormwater and sediment control BMPs



Figure 11: Photo taken from the access road on the south end of the location, facing east. Photo shows project area, and stormwater control ditch on the southern perimeter of the location.



Figure 12: Photo taken from pipe adjacent to the access road on the south end of the location. Photo of exposed hole due to either subsidence or wildlife.



Figure 13: Photo taken from the southeast corner of the project area facing north. Photo shows project and interim areas. Spoils stockpile berm to the right of photo.



Figure 14: Photo taken from the southeast corner of the interim area facing west. Photo shows stormwater diversion ditch.



Figure 15: Photo taken from the southeast corner of the interim area facing northeast. Photo shows stormwater diversion ditch, and spoils stockpile berm.



03.03.2016 13:50

Figure 16: Photo taken from the spoils stockpile berm on the east end of the location, facing west. Photo shows interim and project areas.



03.03.2016 13:50

Figure 17: Photo taken from the spoils stockpile berm on the east end of the location, facing northwest. Photo shows interim and project areas.



Figure 18: Photo taken from the spoils stockpile berm on the east end of the location, facing north. Photo shows soils on berm, and interim area.



Figure 19: Photo taken from the spoils stockpile berm on the east end of the location, facing north. Photo shows soils on berm, and interim area.



Figure 20: Photo taken from the northeast corner of the project area, facing west. Photo shows containment berm on the northern perimeter of the location, and the drill cuttings.



Figure 21: Photo taken from the northeast corner of the project area, facing west. Photo shows spoils stockpile to the left, and containment berm on the east perimeter of the project area.



Figure 22: Photo taken from the northeast corner of the project area, facing east. Photo shows spoils stockpile on the right of the photo, and the stormwater diversion ditch on the left. .



Figure 23: Photo taken from the north end of the project area, facing north. Photo of what appears to be ~15-20 feet of tubing equipment in the interim area.



Figure 24: Photo taken from the northern end of the project area, west of the drill cuttings, facing south. Photo shows straw wattles used as a stormwater and sediment control BMP around cuttings.



Figure 25: Photo taken from the northern end of the project area, west of the drill cuttings, facing east. Photo shows straw wattles used as a stormwater and sediment control BMP around cuttings



Figure 26: Photo taken from the northwest corner of the location, facing south. Photo shows project and interim areas. Note topsoil stockpile to the right of the photo.



Figure 27: Photo taken from the northwest corner of the location, facing east. Photo shows project and interim areas, and stormwater diversion ditch.



Figure 28: Photo taken from northwest corner of the location, facing west. Photo of pipeline. Photo shows stormwater erosion occurring onto pipeline flowing onto project location and into diversion ditch.



Figure 29: Photo taken from the topsoil stockpile on the west end of the location. Photo shows vegetation establishing on the interim area.



Figure 30: Photo taken from the southwest corner of the location, facing north. Photo shows interim and project areas. Note vegetation is predominantly undesirable weedy plant species.



Figure 31: Photo taken from the southwest corner of the location, facing east. Photo shows project area and stormwater control dircth.



Figure 32: Photo taken from the center of the location, facing northeast. Photo shows workers repairing stormwater control BMPs.