

## Construction Inspection



**Photo 1.** Photo taken from eastern location, facing North. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 2.** Photo taken from eastern location, facing South. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 3.** Photo taken from northeast location, facing West. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 4.** Photo taken from northwest location, facing South. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 5.** Photo taken from western location, facing East. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 6.** Photo taken from southwest location, facing South. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 7.** Photo taken from southwest location, facing East. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 8.** Photo taken from southern location, facing Northeast. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 9.** Photo taken from southeast location, facing North. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 10.** Photo taken from eastern location, facing West. Topsoil salvage in process.

## Construction Inspection



**Photo 11.** Photo taken from central location, facing towards topsoil salvage pile. Topsoil salvage in process.