



photo 1: Aerial image of the location taken on October of 2015.



photo 2: Facing south toward the location.



photo 3: Vegetation has not established at the disturbed area north of the location.

Lat/Long: 38.42183/-103.01434



photo 4: Pipe riser remains north of the location. Lat/Long 38.42165/-103.01427



photo 5: South side of the location facing north.



photo 6: Compacted, oil stained soil remains on location. Lat/Long:38.42056,-103.01367.



photo 7: Facing west toward the southwest side of the location. Vegetation has not established.



Photo 8: Southwest side of the location facing east.



Photo 9: Weed debris was noticed throughout the location.



photo 10: Surrounding undisturbed vegetation.