



Photo 1. View of the western portion of the project area from the southwestern corner facing northward. Location is revegetating with grasses such as smooth brome (*Bromus inermis*), sand dropseed (*Sporobolus* sp.), and intermediate wheatgrass (*Thinopyron intermedium*).





Photo 2. View of erosional channel approximately 6 feet deep and 3 feet wide in the eastern portion of the project area.





Photo 3. Stormwater erosional channel in the northeastern portion of the project area.



Photo 4. View of eastern portion of the project area from the northeastern corner facing southward.





Photo 5. View of area along the northern edge of the well pad where concentrated stormwater flows appear to be exiting the well pad and eroding down the slope.





Photo 6. View of stormwater erosion in the western portion of the project area where it appears stormwater flows have breached a sedimented-in diversion channel and are eroding down-slope.



Photo 7. View of the western portion of the project area from the northwestern corner facing southward.





Photo 8. View of the Project area from the northwestern corner facing center.





Photo 9. View of the northern portion of the project area from the northwestern corner facing eastward.





Photo 10. View of musk thistle rosettes within the western portion of the interim reclamation area.