



Photo 1. View of erosion channel that is approximately 3 feet wide and deep in the northeastern portion of the project area. This channel needs to be stabilized.



Photo 2. View of area near well pad entrance where stormwater flows off of the project area toward a culvert. Stormwater BMPs need to be installed here to prevent erosion and sediment discharge.



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*), blue grama (*Bouteloua gracilis*), and Indian ricegrass (*Achnatherum hymenoides*).



Photo 4. View of the project area from the southwestern corner facing center.



Photo 5. View of the western portion of the project area from the southwestern corner facing northward.



Photo 6. View of the eastern portion of the project area from the southern portion facing northward.



Photo 7. View of the northern portion of the project area from the northeastern corner facing westward.