

# Interim Reclamation Inspection

3/10/2016

Operator: Carrizo

Location: 434923

Weld County, CO

NWNW Section 34 T9N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**Figure 1:** Photo taken from access road on the north end of the location, facing east. Photo shows location signs. .



**Figure 2:** Photo taken from the northeast corner of the location, facing west. Photo shows interim and project areas, and stormwater control ditch.



03.10.2016 13:25

**Figure 3:** Photo taken from the northeast corner of the location, facing south. Photo shows interim and project areas, and stormwater control ditch.



**Figure 4:** Photo taken from the east end of the location, facing west. Photo shows erosion occurring at perimeter control berm.



**Figure 5:** Photo taken from the east end of the location, facing south. Photo shows erosion occurring at perimeter control berm.



**Figure 6:** Photo taken from the southeast corner of the location, facing north. Photo shows interim and project areas, and stormwater control ditch. Note vegetation is predominantly undesirable weedy plant species.



**Figure 7:** Photo taken from the southeast corner of the location, facing west. Photo shows interim and project areas.



**Figure 8:** Photo taken from the southeast corner of the location, facing east. Photo shows interim and project areas.



**Figure 9:** Photo taken from the southwest corner of the location, facing north. Photo shows interim and project areas.



**Figure 10:** Photo taken from the southwest corner of the location, facing northeast. Photo shows project area.



**Figure 11:** Photo taken from the western end of the project area, facing west. Photo shows erosion occurring on location.



**Figure 12:** Photo taken from the western end of the project area, facing northwest. Photo shows erosion occurring on location.



**Figure 13:** Photo taken from the western end of the project area, facing southwest. Photo shows erosion occurring on location.



03.10.2016 13:34

**Figure 14:** Photo taken from the western end of the project area, facing west. Photo shows erosion occurring on location.



**Figure 15:** Photo taken from the northwest end of the project area, facing northwest. Photo shows erosion occurring on location.



**Figure 16:** Photo taken from the northwest end of the project area, facing northwest. Photo shows erosion occurring on location.



**Figure 17:** Photo taken from the northwest corner of the location, facing south. Photo shows vegetation on the current interim area. Note vegetation is predominantly undesirable weedy plant species.



**Figure 18:** Photo taken from the northwest corner of the location, facing east. Photo shows vegetation on the current interim area. Note vegetation is predominantly undesirable weedy plant species.



**Figure 19:** Photo taken from the northwest corner of the location. Photo shows vegetation on the current interim area. Note vegetation is predominantly undesirable weedy plant species.



**Figure 20:** Photo taken from the northwest corner of the location, facing southeast. Photo shows project area.



**Figure 21:** Photo taken from the producing wells, facing west. Photo shows signs missing from wells.



**Figure 22:** Photo taken from the producing wells, facing southeast. Photo shows signs missing from wells.



**Figure 24:** Photo taken from gas lift engine facility on the north end of the location. Photo shows pipe covered in oil, and stained soil.