

Construction Inspection

3/11/2016

Operator: Whiting

Location ID: 442408

Weld County, CO

SENE Section 7 T10N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from access road, northwest of location, facing east. Photo shows stormwater and sediment control ditch construction in process on perimeter of location.



Figure 2: Photo taken from access road, northwest of location, facing southeast. Photo shows stormwater and sediment control ditch construction in process on perimeter of location.



Figure 3: Photo taken from the northwest corner of the location, facing east. Photo shows stormwater control ditch BMP installation in process.



Figure 4: Photo taken from the northwest corner of the location, facing south. Photo shows stormwater control ditch BMP installed on perimeter of location.



03.11.2016 13:35

Figure 5: Photo taken from the southwest corner of the location, facing east. Photo shows stormwater control ditch BMP installed on perimeter of location.



Figure 6: Photo taken from the southeast corner of the location, facing west. Photo shows stormwater control ditch BMP installed on perimeter of location. Note the grade of the slope, velocity checks are advised in areas with steeper grades.



Figure 7: Photo taken from the southeast corner of the location, facing northeast. Photo shows stormwater control ditch BMP installed on perimeter of location. Note the grade of the slope, velocity checks are advised in areas with steeper grades.



Figure 8: Photo taken from the east of the location, facing west. Photo shows location.



Figure 9: Photo taken from the east of the location, facing west. Photo shows location.



Figure 10: Photo taken from the east of the location, facing northwest. Photo shows location.



Figure 11: Photo taken from the northeast corner of the location, facing southeast. Photo shows stormwater control ditch BMP installed on perimeter of location. Note the grade of the slope, velocity checks are advised in areas with steeper grades.



03.11.2016 13:43

Figure 12: Photo taken from the northeast corner of the location, facing west. Photo shows stormwater control ditch BMP installed on perimeter of location.