

Final Reclamation Inspection

3/11/2016

Operator: Noble Energy

Location ID: 327002

Weld County, CO

SESE Section 34 T9N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from access road, southeast of location facing north.



Figure 2: Photo taken from the southeast corner of the location, facing north. Photo shows location has not achieved uniform vegetation.



Figure 3: Photo taken from the southeast corner of the location, facing west. Photo shows location has not achieved uniform vegetation.



Figure 4: Photo taken from the south end of the location, facing southwest. Photo shows gathering riser remaining on location.



Figure 5: Photo taken from the south end of the location, facing north. Photo shows trash debris on location.



Figure 6: Photo taken from the southwest corner of the location, facing east. Photo shows location has not achieved uniform vegetative cover.



Figure 7: Photo taken from the southwest corner of the location, facing north. Photo shows location has not achieved uniform vegetative cover.



Figure 8: Photo taken from the west end of the location, facing east. Photo shows straw wattle BMP improperly maintained. Wattle is accelerating stormwater around, rather than pooling, causing erosion.



Figure 9: Photo taken from the northwest corner of the location, facing south. Photo shows vegetation on location.



Figure 10: Photo taken from the northwest corner of the location, facing east. Photo shows vegetation on location.



Figure 11: Photo taken from the north end of the location, facing south. Photo shows location has not achieved uniform vegetative distribution. Undesirable weedy plant species such as puncture vine shown in photo.



Figure 12: Photo taken from the northeast end of the location, facing west. Photo shows location has not achieved uniform vegetative distribution.



Figure 13: Photo taken from the northeast end of the location, facing south. Photo shows location has not achieved uniform vegetative distribution.



Figure 14: Photo taken from the east end of the location, facing west. Photo shows location has not achieved uniform vegetative distribution.



Figure 15: Photo taken from the northeast end of the location, facing west. Photo shows vehicle rutting; vehicles driving on reclamation area.