



**photo 1:** Facing toward the access road from the county road.



**photo 2:** Facing north toward county road at the beginning of the access road.





**photo 3:** Facing west toward the access road.



**photo 4:** An erosion channel has developed which is directing sediment towards the county road.





**photo 5:** Signs of erosion near the gate.



**photo 6:** Sediment has filled in the cattle guard.





**photo 7:** Facing back toward the east, there are signs of erosion along the access road.



**photo 8:** Facing southwest toward the location.





**photo 9:** Facing toward the northwest cut slope side of the pad, which is not adequately stabilized.



**photo 10:** Noticed oil stains around the well head.





**photo 11:** Oil stained surface near the wellhead.



**photo 12:** South side of the location facing east.