

Interim Reclamation Inspection



Photo 1. Photo taken from southern location, facing North towards the eight (8) PR wells. Interim reclamation in process- visible evidence of seeding.

Interim Reclamation Inspection



Photo 2. Photo taken from southern location, facing East. Interim reclamation in process- visible evidence of seeding.

Interim Reclamation Inspection



Photo 3. Photo taken from southeast location, facing North. Need to address ponding water. This is only causing additional runoff onto eastern interim reclamation area.

Interim Reclamation Inspection



Photo 4. Photo taken from the eastern location, facing West. Interim reclamation area needs to be stabilized to minimize erosion while vegetative growth establishes. Erosion is occurring along portions of the eastern and northern interim reclamation area.

Interim Reclamation Inspection



Photo 5. Photo taken from northeast location, facing West. Interim reclamation in process- visible evidence of seeding.

Interim Reclamation Inspection



Photo 6. Photo taken from the northern location, facing South. Interim reclamation area needs to be stabilized to minimize erosion while vegetative growth establishes. Erosion is occurring along portions of the eastern and northern interim reclamation area.

Interim Reclamation Inspection



Photo 7. Photo taken from the northern location, facing South. Interim reclamation area needs to be stabilized to minimize erosion while vegetative growth establishes. Erosion is occurring along portions of the eastern and northern interim reclamation area.

Interim Reclamation Inspection



Photo 8. Photo taken from the western location, facing East. Need to remove waste material from location.

Interim Reclamation Inspection



Photo 9. Photo taken from the western location, facing East. Need to remove waste material from location.

Interim Reclamation Inspection



Photo 10. Photo taken from the western location, facing South. Need to remove waste material from location.

Interim Reclamation Inspection



Photo 11. Photo taken from western location, facing West along south lease road. Interim reclamation in process- visible evidence of seeding.

Interim Reclamation Inspection



Photo 12. Photo taken from western location, facing West along north lease road. Interim reclamation in process- visible evidence of seeding.