

Photo#1:
View South over Location



March 15, 2016

Inspection Photos Minerals Engineering DA
029-60003

Photo#2:
View East over Location



Photo#3:
View West over Location

