

Interim Reclamation Inspection- Tank Battery Location



Photo 1. Photo taken of Tank Battery sign, servicing Blaine 42-28 (API# 123-10578).

Interim Reclamation Inspection- Tank Battery Location



Photo 2. Photo taken from the southern tank battery location, facing Southwest. Need to control stormwater runoff that minimizes erosion and transport of sediment offsite per Rule 1002. Erosion and transport of sediment is occurring south, offsite, onto cropland.

Interim Reclamation Inspection- Tank Battery Location



Photo 3. Photo taken from the southern tank battery location, facing Northeast. Need to control stormwater runoff that minimizes erosion and transport of sediment offsite per Rule 1002. Erosion and transport of sediment is occurring south, offsite, onto cropland.

Interim Reclamation Inspection- Tank Battery Location



Photo 4. Photo taken from the south of tank battery location, facing North. Need to control stormwater runoff that minimizes erosion and transport of sediment offsite per Rule 1002. Erosion and transport of sediment is occurring south, offsite, onto cropland.