

## Interim Reclamation Inspection- Lease Road



**Photo 1.** Photo taken from lease road, facing East. Need to control stormwater runoff that minimizes erosion and transport of sediment offsite per Rule 1002. Erosion and transport of sediment is occurring east, offsite, onto cropland.



## Interim Reclamation Inspection- Lease Road



**Photo 2.** Photo taken east of lease road approximately 15 meters, facing East. Photo illustrating erosion and transport of sediment on cropland.

## Interim Reclamation Inspection- Lease Road



**Photo 3.** Google Earth aerial photo taken 10/9/2015. Erosion and transport of sediment initiates on the lease road and travels east through cropland.