



photo 1: Facing west toward the location.



photo 2: Facing toward production equipment. New gravel has been placed around the equipment.



photo 3: Noticed oil on the skid of the separator. Pioneer employee nearby was notified.



photo 4: Northwest corner of the location facing southeast.



photo 5: North side of the location facing east.



photo 6: Facing toward the northwest corner. Oil fluid noticed in the previous inspection appears to have been cleaned up.