



photo 1: Facing south toward the location.



photo 2: Facing toward production equipment. New disturbance has been created around the equipment.



photo 3: Wellhead at the south side of the location. Water leak has been repaired.



photo 4: Facing toward the wellhead at the north side of the location.