



Photo#1: Overview of Location to North



Photo#2: View of Location to South, showing sagging fence in disrepair.



Photo#3: View of Well head to East



Photo#4: View West over Wellhead

March 16, 2016

Inspection Photos FRAM Operating Hamilton SI 029-06101



Photo#5: View of Wellhead showing open area between Conductor and Surface casing that needs to be covered.