



photo 1: Facing north toward the wellhead and equipment at the location.



photo 2: West side of the location facing east.



photo 3: South side of the location facing north.



photo 4: East side of the location. The slope is not well stabilized in this area and may need additional BMP's installed.