

## Construction Inspection



**Photo 1.** Photo taken from northern location (entrance), facing East. Stormwater and sediment control BMPs installed in center of photo (surface roughening).



## Construction Inspection



**Photo 2.** Photo taken from northern location (entrance), facing West. Stormwater and sediment control BMPs installed in center of photo (surface roughening).



## Construction Inspection



**Photo 3.** Photo taken from northwest location, facing South. Stormwater and sediment control BMPs installed in center of photo (ditch/berm and surface roughening).



## Construction Inspection



**Photo 4.** Photo taken from southwest location, facing East. Stormwater and sediment control BMPs installed in center of photo (ditch/berm and surface roughening).



## Construction Inspection



**Photo 5.** Photo taken from southeast location, facing West. Stormwater and sediment control BMPs installed in center of photo (ditch/berm and surface roughening).



## Construction Inspection



**Photo 6.** Photo taken from southeast location, facing North. Stormwater and sediment control BMPs installed in center of photo (surface roughening).



## Construction Inspection



**Photo 7.** Photo taken from northern location, facing South. Topsoil salvage in process.