

Interim Reclamation Inspection




Photo 1. Photo taken of PR well sign for API 123-13722.

Interim Reclamation Inspection



Photo 2. Photo taken south of location, facing North. Weeds have been removed from around wellhead.