

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
03/26/2016
Document Number:
679500096
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>272178</u>	<u>320511</u>	<u>AXELSON, JOHN</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 10311
 Name of Operator: SYNERGY RESOURCES CORPORATION
 Address: 20203 HIGHWAY 60
 City: PLATTEVILLE State: CO Zip: 80651

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Maclaren, Joe		joe.maclaren@state.co.us	
Rasmuson, Craig	970-737-1073	crasmuson@syrginfo.com	
Pennington, Dave		dpennington@syrginfo.com	Synergy Inspection
Brian, Jerry		jbrian@syrginfo.com	

Compliance Summary:

QtrQtr: NWNE Sec: 2 Twp: 1S Range: 68W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/15/2013	668701155	PR	FR	SATISFACTORY	P		No
02/03/2010	200237578	PR	PR	SATISFACTORY			No
01/04/2005	200064202	CC	DG	SATISFACTORY		Pass	No

Inspector Comment:

Inspection was performed in response to Complaint #200439230. Complainant was concerned about work that has been performed at location specifically if there is any soil or groundwater contamination. Synergy reported historic flowline release on 12/10/15 (Spill Doc #400951704). They performed source removal and delineated the extent of soil and groundwater impacts. Information was provided in Form 27 (Remediation Project #9504) submitted to COGCC 2/16/16. Synergy proposed soil shredding to treat additional impacted soil and implemented the plan in February 2016. Final documentation is pending. Production facilities were still dismantled at time of inspection. Location was covered with snow from recent storm. No open excavations were observed. Checked stream adjacent to location and did not observe any sediment transport into the stream or any areas of hydrocarbon sheen. Synergy is continuing to complete the remedial actions and restore surface under the approved Form 27.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272178	WELL	PR	04/20/2005	GW	001-09507	STANDLEY 2-2	EI <input checked="" type="checkbox"/>
272179	WELL	PR	04/20/2005	GW	001-09506	STANDLEY 1-2	EI <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Predrill

Location ID: 272178

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 272178 Type: WELL API Number: 001-09507 Status: PR Insp. Status: EI

Facility ID: 272179 Type: WELL API Number: 001-09506 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Complaint:				
Tracking Num	Category	Assigned To	Description	Incident Date
200439230	GROUND WATER	Axelson, John	Location is described as E 168th Ave and Weld Co Rd 11. Standley Well Owner: Synergy Complainant states: Synergy has been doing major construction on site for several weeks with moving dirt, etc. No notice was given to neighbors so we are assuming they are not adding to the wells. It appears they are replacing aging pipes that are corroded. That is of concern - we would like to know if that has led to any ground water contamination or exposure - any spills and soil contamination. They have left big holes in the ground and rain and snow melt has accumulated in open pits/holes. I can provide pictures if necessary. Concern with corroded pipes -has it led to any ground water contamination?	03/22/2016

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? _____
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679500096	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3817515
679500097	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3817512
679500098	Former flowline staged for disposal	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3817513
679500099	Stream adjacent location looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3817514