

Interim Reclamation Inspection



Photo 1. Photo taken of PR well sign for API 123-13697.

Interim Reclamation Inspection



Photo 2. Photo taken of PR well sign for API 123-25680.

Interim Reclamation Inspection



Photo 3. Photo taken southwest of location, facing Northeast. Weeds have been removed from around wellhead.