

## Interim Reclamation Inspection



**Photo 1.** Photo taken from northwest location, facing Southwest. Wattles have been reinstalled along the western perimeter of the location.



## Interim Reclamation Inspection



**Photo 2.** Photo taken from western location, facing Southwest. Wattles have been reinstalled along the western perimeter of the location.



## Interim Reclamation Inspection



**Photo 3.** Photo taken from southwest location, facing South. Wattles have been reinstalled along the western perimeter of the location.



## Interim Reclamation Inspection



**Photo 4.** Photo taken from western location. Wattles have been reinstalled along the western perimeter of the location. Overlapping wattles behind each other can be helpful to control sediment. Otherwise, wattles must butt the second wattle tightly against the first wattle.