



photo 1: Facing east towards the access road standing at county road 63.



photo 2: Cattle guard is not filled with sediment and no maintenance issues were noticed.



photo 3: Facing east along the access road.



photo 4: View of the road base material along the access road.



photo 5: Facing east showing surrounding pasture vegetation along the access road.



photo 6: Facing northeast from the access road toward the vegetated drainage ditch which is directed out into the pasture.



photo 7: Facing east along the access road.



photo 8: Facing east along the access road.



photo 9: Facing east toward the point where access road turns north to the location. Red line indicates approximate point where reclamation work appears to begin.



photo 10: Facing back towards the west at the access road. Red line indicates approximate point where reclamation work appears to begin.



photo 11: Facing north along the former access road. Access road turns to the north at this point.



photo 12: It appears that the access road was ripped and decompacted starting at this point which goes north toward the location.



photo 13: Facing north along the former access road.



photo 14: Noticed vegetation germination which appears to be an undesirable species (Kochia).



photo 15: Facing north toward the location.



photo 16: Center of the location facing northeast. Did not notice vegetation germination in this area.



photo 17: Noticed weed debris (Kochia) with Kochia beginning to germinate under this debris.



photo 18: Northwest corner of the location facing southeast toward the location.



photo 19: Northwest corner of the location facing south toward the location.



photo 20: Facing north toward the surrounding undisturbed pasture.