



Photo 1. View of the western portion of the project area from the northwestern corner facing southward. An irrigation ditch runs adjacent to the western edge. Revegetation is largely comprised of soft brome (*Bromus inermis*).



Photo 2. View of the project area from the northwestern corner facing center.





Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward. Irrigation pipe is being stored in the northern and eastern portions of the interim reclamation area.



Photo 4. View of the eastern portion of the project area from the northeastern corner facing southward.