



photo 1: Aerial image of the location taken on 6/13/2014.



photo 2: Beginning of the access road facing southwest.



photo 3: Facing southwest along the access road. There is undesirable vegetative debris that is present.



photo 4: View of undesirable vegetative debris with undesirable vegetation (Kochia) beginning to germinate along the access road.



photo 5: North side of the location facing south. Location bare of vegetation approx. 120'x120'.



photo 6: South side of the location facing north. Location bare of vegetation approx. 120'x120'.



photo 7: East side of the location facing west. Location bare of vegetation approx. 120'x120'.



photo 8: Facing east at the surrounding undisturbed pasture.