



photo 1: Facing south at the beginning of the access road.



photo 2: Facing south along the access road which has not been reclaimed.



photo 3: Gravel material remains along the access road. The shovel indicates soil compaction issues along the access road.



photo 4: North side of the location facing south.



photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: East side of the location facing west at the location.



photo 10: Facing west at the surrounding undisturbed vegetation.