

Interim Reclamation Inspection



Photo 1. Photo taken east of location, facing West. Interim reclamation areas no longer in use have been reduced.

Interim Reclamation Inspection



Photo 2. Photo taken east of location, facing Southwest. Cropland has been replaced to relative contour and tilled to re-establish a proper seedbed. Cropland will be evaluated at a future date to ensure compliance with Rule 1003 regarding revegetation.

Interim Reclamation Inspection



Photo 3. Photo taken east of location, facing East. Cropland has been replaced to relative contour and tilled to re-establish a proper seedbed. Cropland will be evaluated at a future date to ensure compliance with Rule 1003 regarding revegetation.

Interim Reclamation Inspection



Photo 4. Photo taken east of location, facing North. Cropland has been replaced to relative contour and tilled to re-establish a proper seedbed. Cropland will be evaluated at a future date to ensure compliance with Rule 1003 regarding revegetation.