



Figure 1 - Well sign.



Figure 2 - Wellhead.





Figure 3 - Damaged fence, stained soil, chemical storage, and unused equipment on west side of well pad.



Figure 4 - Damaged fence, chemical storage container, unused propane tank, and additional debris at northwest corner of well pad.





Figure 5 - Oil-stained soil at former pump jack location.



Figure 6 – Low area observed northeast of wellhead (possible former pit location).





Figure 7 - Excavation and bare soil observed northwest of well pad.



Figure 8 - Tank battery sign.





Figure 9 - West side tank battery fence in need of repair.



Figure 10 - Unused propane tank, weeds, wooden debris, and exposed flowlines at former heater treater location (west of tank battery).





Figure 11 - Low points in tank battery berm (NW corner) and uncontrolled weeds.



Figure 12 - Western crude oil tank, low berm, and uncontrolled weeds at SW corner of tank battery.





Figure 13 - Unused thief hatch and oil-stained soil west of crude oil tank.



Figure 14 - Oil-stained soil, erosion rills, and seeps from crude oil tanks.





Figure 15 - Oil-stained soil at leaking valves on crude oil tanks.