

Interim Reclamation Inspection



Photo 1. Photo taken from southern location, facing East. Stormwater controls have been installed along southern, eastern and northern location areas.

Interim Reclamation Inspection



Photo 2. Photo taken from eastern location, facing North. Stormwater controls have been installed along southern, eastern and northern location areas.

Interim Reclamation Inspection



Photo 3. Photo taken from northern location, facing West. Stormwater controls have been installed along southern, eastern and northern location areas.

Interim Reclamation Inspection



Photo 4. Photo taken from southern location, facing North. Ponding water has been filled in to control additional runoff onto eastern location.