

Interim Reclamation Inspection



Photo 1. Photo taken of PR well sign for API 123-14790.

Interim Reclamation Inspection



Photo 2. Weeds have been removed around wellhead.