



**photo 1:** Facing southeast toward the location along the access road.



**photo 2:** Facing south toward the cut face of the location where reclamation and stormwater controls have recently been installed.





**photo 3:** Facing south toward the location.



**photo 4:** East side of the location facing south.





**photo 5:** Noticed vegetation beginning to germinate in the reclamation area.



**photo 6:** Northeast side of the location facing south.





**photo 7:** Southeast side of the location facing north.



**photo 8:** Southeast side of the location facing northwest.