



photo 1: Facing northwest toward the access road.



photo 2: Culvert is maintained at beginning of the access road.



photo 3: Facing west toward the location.



photo 4: Facing west toward the north side of the location.



photo 5: Facing southwest toward onsite pit.



photo 6: Southeast side of the location facing north.



photo 7: Southeast side of the location facing northwest.



photo 8: West side of the location facing north.