



photo 1: Facing east along the access road toward the location.



photo 2: Facing east toward the location.



photo 3: Rip/rap rock and sediment trap has been installed at the northwest corner of the location.



photo 4: North side of the location facing west. Vegetation is not well established in this area.



photo 5: Northeast side of the location facing southwest. Vegetation is not well established in this area.



photo 6: Southeast side of the location facing north. Vegetation is not well established in this area.