

Photo#1:

View North over Well



Photo#2:

View South over Well



April 24, 2016

Inspection Photos: Lloyd & Lowell 1 API# 077-40017



Photo#3:

View East over well

Arrow shows position of Irrigation ditch



Photo#4:

View West over Well






Photo#5:

Burbling Liquids at base of and in center of Plug



Photo#6:





Photo#7:

Oily / tarry Scum on surface around Well Head; Mouse was seen to run over area without submerging



Photo#8:





Photo#9:

Oil saturated Vegetation at Pool edge.



Photo#10:

Slew area formed by Well discharge to SW

